

- Weld the mounting lugs (6) in that position.